



CDM20802_Setup driver adapted to WIN2000-XP-VISTA-WIN7.0-X86-X64 system.

Installation method: (Recommended method 1)


- 1、 Use the driver CDM20802_Setup. Exe, double-click the installation can be, and then plug in equipment will be identified.
- 2、 Use .inf file installation, suitable for method 1 invalid user.
 - a) Plug in equipment, execute search driver installation guide, select the folder that the directory for inf drive.
 - b) Continuous install twice
- 3、 Connected equipment, check the computer “COM” port if in the range of “COM1-COM10”, if “YES”, the equipment will be connected with computer normally. Or please set it up: Computer—device management—port (COM and LPT)—USB serial port




Open the USB Serial Port attribute,



Click **Avancé...**,



Change the port into the range of COM1-COM10, click OK,



Click OK; DONE.